

**Appendix B3:  
CVWD Shoofly Biological Survey Notes**

Date: 12/19/24 Observer: S. Watts Location: Thousand Palms Channel #42nd Project: TPC Shooply

Weather: ~80°F (26°F), slight haze, calm

Start Time: 10:20

End Time: 11:12

Reason for Visit:

Thousand Palms Channel Shooply, Make sure consistent w/ MM in MAND for TPC slope lining

Area Description:

Highly disturbed next to roadway, Mixture of Blendsand, trash, cable & concrete, but mostly native plants

Survey Findings:

Findings seem that current MM will cover impacts to the area but will review later.

GIS Recorded: YES/NO GIS Name(s): TPC Shooply

Active Burrowing Owls: YES/NO Location(s):

Active MBTA Nest: YES/NO Location(s):

CNDDDB Needed: YES/NO Location(s):

Animal Species Seen:

None seen. Tracks: CORA, Uta sp, Coyote,

Plant Species Seen:

Atriplex polycarpa, Atriplex canescens, Palatopsis arida, Salsola tragus

Site Visit Photos: YES/NO

LINK: TPC Shooply